



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION VI

HOUSTON BRANCH

6608 HORNWOOD DRIVE

HOUSTON, TEXAS 77074

Date: 7/30/87

Subj.: Laboratory results for the Grant Road Site.

From: *M. Kendall Young*
M. Kendall Young, Chief, Inorganic section, 6E-HL

To: Diana G. Ayers, Chief, Houston Branch, 6E-H

Attached are laboratory results for the subject site. Four (4) soil samples were received on 6/30/87 to be analyzed for the hazardous substance list (HSL) metals and cyanide. The laboratory numbers assigned were 7TFAKCl201 thru 7TFAKCl204.

The cyanide value for sample 7TFAKCl201 is questionable because an interfering substance caused a cloudy distillate. The nature of this material or its effect upon the cyanide analysis could not be determined. The value for cyanide in this sample appears to be below the detection limit of 0.05 mg/kg.

This is a final report.

9024368



Attachments (4)